



Nov / 2009

Genuine UI2

Counterfeit





2

Cavity mark here

No Cavity mark

2


Difference by appearance

- 1 Colour of Case : Countrefeit more yellow tinged
 - 2 Case: Counterfeit has no cavity mark
 - 3 Lead wire: marking is different











Function

Operating Temperature tends to go higher than upper limit (counterfeits). Resetting dosen't synchronize between bimetal and contacts(counterfeits). Internal structure:upside down, insufficient insertion of switch mechanism which resulted in uneven heat response (some counterfeits).