

We have renovated the roof of our main-building for enhancing earthquake and water-resistance.

Duration: November ~ December/end 2014

As the first step of renovation of our main-building for enhancing earthquake-resistance, we have removed those existing heavy items such as fence, base concrete blocks, advertising sign, lightning rod, etc. from the roof and reinforced there.

We are planning to advance our anti-earthquake renovation works step by step from the roof to the lower levels of our main-building.

We will also aim to achieve "clean room" at our production area in order to supply higher quality products.

We apologize for causing any inconvenience to you due to the renovation works. Your understanding and cooperation to us would be highly appreciated.

